

Oil Field Environmental Incident Summary

Incident: 20150519165750 **Date/Time of Notice:** 05/19/2015 16:57

Responsible Party: PETRO-HUNT, L.L.C.

Well Operator: PETRO-HUNT, L.L.C.

Well Name: SYVERSON 156-99-30B-31-4H

Field Name: EAST FORK

Well File #: 26098

Date Incident: 5/19/2015 **Time Incident:** 10:30

Facility ID Number:

County: WILLIAMS

Twp: 156

Rng: 99

Sec: 30

Qtr:

Location Description:

Submitted By: Shawn Reisenauer

Received By:

Contact Person: Shawn Reisenauer
390 119th Ave. SW
Killdeer, ND 58640

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	4	Barrels	4	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

none

Areal Extent:

Potential Environmental Impacts:

none

Action Taken or Planned:

All fluids and materials on site are being vacced up and oil on tank cleaned.

Wastes Disposal Location: Secure Disposal

Agencies Involved:

Updates

Date: 5/20/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.